



Service Bulletin

SB 242 - December 2013

1 of 1

18513 Euclid Avenue

Cleveland, Ohio 44112-1084

Phone: 216-486-1313 Fax: 216-486-9776

www.meyerproducts.com

E-mail warranty@meyerproducts.com

SUBJECT: 07347 Plow Light Module

To all concerned:

The 07347 Plow Light Module was redesigned in July of this year to include the Low Beam Disable Module (07625) on its circuit board. We have discovered that when this new redesigned module is used on vehicles with a positive ground headlight system, the plow lights will not work in low beam. The affected vehicles are those that require the 07106 (1994-2002 Dodge), 07108 or 07185 (1999-2002 GM) light adapters. Below is a list of batch codes printed on the back of the modules that have the low beam disable built in.

BN: 090713

BN: 260713

BN: 161013

Modules without the above batch codes will work since they do not have the low beam disable built into them. If you do not have modules without the above batch codes, please contact Customer Service. Meyer Products will ship out the replacement modules at no charge, to use on vehicle's with positive ground lighting only.

We have redesigned the module so it will work with both negative and positive ground headlight systems. The new redesigned module part number will change from 07347 to 07347X and will be available the week of December 16th 2013.



Example: The BN: 291010 does not have the low beam disable built in.

	Route To:			
Initial	President/Owner	Sales Manager	Service Manager	Parts Manager